

**REPÚBLICA DOMINICANA**  
**INSTITUTO DOMINICANO DE AVIACIÓN CIVIL**  
**GESTION DE INFORMACIÓN AERONÁUTICA (AIM)**

Apartado Postal 1180, Tel. 221-7909, Santo Domingo, D.N., AILA, edificio Norge Botello Tel. (809) 274-4322 ext. 2293, 2301 Fax 549-0402

**AIM DOMINICAN REPUBLIC**  
**WEB SITE** : aip.idac.gov.do  
**AFTN** : MDSYNYX  
**E-MAIL** : ais@idac.gov.do  
pub@idac.gov.do



**List of valid NOTAM**  
**FEB- 2018**

**THE FOLLOWING NOTAM SERIE "A" STILL IN FORCE AT 1801312359**

<b>2017:</b>	<b>0338</b>	<b>0339</b>	<b>0446</b>	<b>0451</b>	<b>NIL</b>		
<b>2018:</b>	<b>0002</b>	<b>0003</b>	<b>0004</b>	<b>0011</b>	<b>0014</b>	<b>0018</b>	<b>0019</b>

**AIS INTEGRATED PACKAGE: LATEST PUBLICATIONS**

<b>AIP REGULAR AMDT:</b>	<b>NOV-30-2012</b> <b>NOV-30-2017</b>	<b>7-12</b> <b>NIL</b>
<b>AIP AIRAC AMDT:</b>	<b>JAN-04-2018</b>	<b>1-18</b>
<b>AIRAC EFFECTIVE DATES:</b>	<b>FEB-01-2018</b> <b>MAR-01-2018</b> <b>MAR-29-2018</b>	<b>NIL</b> <b>2-18</b> <b>NIL</b>
<b>CURRENT AIP/ SUP:</b>		<b>2016/2017</b>
<b>GEN:</b>		<b>NIL</b>
<b>ENR:</b>		<b>NIL</b>
<b>AD:</b>		<b>NIL</b>
<b>CURRENT/AIC:</b>		<b>2008/2010/2011/2016/2018</b>
<b>GEN:</b>	<b>JAN-01-2018</b> <b>FEB-08-2016</b> <b>JUL-21-2011</b> <b>AUG-04-2008</b> <b>NOV-27-2008</b>	<b>No. 01-18</b> <b>No. 01-16</b> <b>No. 01-11</b> <b>No. 02-08</b> <b>No. 05-08</b>
<b>ENR:</b>	<b>DEC-13-2010</b> <b>NOV-27-2008</b> <b>NOV-27-2008</b>	<b>No. 02-10</b> <b>No. 03-08</b> <b>No. 04-08</b>
<b>AD:</b>	<b>NOV-27-2008</b>	<b>No. 04-08</b>
<b>Monthly list of valid NOTAM:</b>	<b>FEBRUARY-01-2018</b>	<b>FEB</b>

<b>NR</b>	<b>DATE</b>	<b>TEXT</b>
<b>A0338/17</b>	<b>17-09-28</b>	<b>MDSI / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP</b> <b>1710120000 / PERM</b> THRESHOLD ELEVATION CHANGED RUNWAY 17 TO 11.99 METRES AND RUNWAY 35 TO 17.69 METRES REFERENCE TO AIP DOMINICAN REPUBLIC PAGES MDSI AD 2-6 AND 2-15 DATED 12 OCT 17.
<b>A0339/17</b>	<b>17-09-28</b>	<b>MDSI / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP</b> <b>1710120000 / PERM</b> TOUCHDOWN ZONE ELEVATION CHANGED RUNWAY 17 TO 16.36 METRES AND RUNWAY 35 TO 16.98 METRES REFERENCE TO AIP DOMINICAN REPUBLIC PAGES MDSI AD 2-6 AND 2-15 DATED 12 OCT 17.
<b>A0446/17</b>	<b>17-12-20</b>	<b>MDSI / SAN ISIDRO AIR BASE AP (MIL)</b> <b>1712201528 / 1803191527</b> SIS VOR/DME ON FREQUENCY 112.4 MHZ UNSERVICEABLE.

NR	DATE	TEXT
A0451/17	17-12-27	<b>MDBH / MARIA MONTEZ INT'L AP</b> 1712271900 / 1803262359 FIRE AND RESCUE DOWNGRADED TO CATEGORY-2.
A0002/18	18-01-05	<b>MDSB / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP</b> 1802100200 / 1802101400 RUNWAY 17/35 CLOSED DUE TO MEN AND EQUIPMENT WORKING.
A0003/18	18-01-05	<b>MDCS / SANTO DOMINGO FIR</b> 1801051944 / 1802030400 DAILY 1200-0400 CAPTIVE BALLOON WILL TAKE PLACE ON COORDINATE: 18°40'21"N 068°25'07"W (SIERRA PARIMA MELIA HOTELS) 6.79 NAUTICAL MILES NORTH WEST OF PUNTA CANA INTERNATIONAL AIRPORT FROM GROUND TO 500 FEET ABOVE GROUND LEVEL.
A0004/18	18-01-09	<b>MDCY / EL CATEY INT'L AP</b> 1801091200 / 1802092200 MEN AND EQUIPMENT WORKING ON RUNWAY 07/25, CAUTION IS ADVISED.
A0011/18	18-01-19	<b>MDCY / EL CATEY INT'L AP</b> 1801192050 / 1802072359 ATIS ON FREQUENCY 132.650 MHZ UNSERVICEABLE DUE TO MAINTENANCE.
A0014/18	18-01-23	<b>MDST / DEL CIBAO INT'L AP</b> 1802050300 / 1802151200 FEBRUARY 05, 06, 08, 12, 13 AND 15 0300-1200 RUNWAY 11/29 CLOSED DUE TO MEN AND EQUIPMENT WORKING.
A0018/18	18-01-30	<b>MDSB / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP</b> 1801301425 / 1804292359 I-CDO ILS GLIDE PATH RUNWAY 17 ON FREQUENCY 329.3 MHZ UNSERVICEABLE DUE TO MAINTENANCE.
A0019/18	18-02-01	<b>MDCS / SANTO DOMINGO FIR</b> 1802011513 / 1802282359 EST CHECKLIST OF NOTAM "A" IN FORCE.
<i>This List of Valid NOTAM cancel the last List of Valid NOTAM JANUARY 2018</i>		