

REPÚBLICA DOMINICANA
INSTITUTO DOMINICANO DE AVIACIÓN CIVIL
SERVICIOS DE INFORMACIÓN AERONÁUTICA

Apartado Postal 1180, Santo Domingo, D. N., Tel. (809) 542-0160, 221-7909, 549-0402, FAX (809) 221-8616, 549-0692

AIS DOMINICAN REPUBLIC
WEB SITE : www.aip.idac.gov.do
AFTN : MDSYNYX
E-MAIL : ais@idac.gov.do
pub@idac.gov.do



Monthly list of valid NOTAM
JUL 06-10

THE FOLLOWING NOTAM SERIE "A" STILL IN FORCE AT 1006302359

2010:	0012	0013	0015	0116	0184	0187	0222	0228	0234
0241	0242	0243	0245	0247	0250	0251	0259	0260	0261
0262	0268	0269							

AIS INTEGRATED PACKAGE: LATEST PUBLICATIONS

AIP REGULAR AMDT	MAY-30-2010 NOV-30-2009	NIL 4-09
AIP AIRAC AMDT	JAN-28-2009	1-10
AIRAC EFFECTIVE DATES	JUL-29-2010 AUG-26-2010	2-10 NIL
CURRENT AIP/ SUP:		2009
GEN :		NIL
ENR :		NIL
AD:	NOV-05-2009	A01-09
CURRENT/AIC:		2008/2010
GEN:	AUG-04-2008 NOV-27-2008	No. 02-08 No. 05-08
ENR:	MAR-20-2010 NOV-27-2008 NOV-27-2008	No. 01-10 No. 03-08 No. 04-08
AD:	NOV-27-2008	No. 04-08
Monthly list of valid NOTAM:	JUL-06-2010	JUL

NR	Date	TEXT
A0012-10	10-01-12	MDBH / MARIA MONTEZ INT'L AP 1001121445/PERM BHO VOR ON FREQUENCY 112.0 Mhz UNSERVICEABLE.
A0013-10	10-01-12	MDBH / MARIA MONTEZ INT'L AP 1001121450/PERM MARIA MONTEZ INTERNATIONAL AIRPORT OPERATING FROM SUNRISE TO SUNSET.
A0015-10	10-01-12	MDBH / MARIA MONTEZ INT'L AP 1001121450/PERM AERODROME OPERATING LIMITED TO VISUAL FLIGHT RULES ONLY.
A0116-10	10-02-26	MDCS / SANTO DOMINGO FIR 1002261545/PERM THE POINT OF NOTIFICATION ASIVO SHALL NOT BE USED FOR INSTRUMENT FLIGHT RULES TRAFFIC DEPARTING FROM ANY DOMINICAN AIRPORT.

NR	Date	TEXT
A0184-10	10-04-13	MDPC / PUNTA CANA INT'L AP 1004132200/1007132130 NEW RUNWAY UNDER CONSTRUCTION, WORK IN PROGRESS AT 760 METERS NORTH OF RUNWAY 09/27.
A0187-10	10-04-15	MDBH / MARIA MONTEZ INT'L AP 1004151800/1007151900 AGGREGATE ASPHALT LOOSE ON FIRST 350 METERS THRESHOLD RUNWAY 12/30. CAUTION ADVISED.
A0222-10	10-05-21	MDBH / MARIA MONTEZ INT'L AP 1005211850/PERM BHO DME ON FREQUENCY 112.0 Mhz UNSERVICEABLE.
A0228-10	10-05-25	MDSD / LAS AMERICAS INT'L AP 1005250400/1007250400 RUNWAY 17/35 FRICTION COEFFICIENT IN THE FIRST THIRD MEASURED BELOW THE LEVEL SPECIFIED IN CIRCULAR CA 1400-03, PART 11.2.6, NUM (3), WILL BE CONSIDERED SLIPPERY SURFACE WHEN WET, CAUTION IS ADVISED, A COPY OF THIS CIRCULAR MAY BE DOWNLOADED FROM: HTTP://WWW.IDAC.GOV.DO/SEGURIDADOPE/CIRCULARES.HTM.
A0234-10	10-05-27	MDPC / PUNTA CANA INT'L AP 1005271720/PERM RUNWAY 09 FRICTION COEFFICIENT IN THE FIRST THIRD MEASURED BELOW THE LEVEL SPECIFIED IN CIRCULAR CA 1400-03, PART 11.2.6, NUM (3), WILL BE CONSIDERED SLIPPERY SURFACE WHEN WET, CAUTION IS ADVISED, A COPY OF THIS CIRCULAR MAY BE DOWNLOADED FROM: HTTP://WWW.IDAC.GOV.DO/SEGURIDADOPE/CIRCULARES.HTM.
A0241-10	10-06-02	MDSI / SAN ISIDRO INT'L AP 1006021800/1009021800 EST SIS VOR ON FREQUENCY 114.5 Mhz ON TEST.
A0242-10	10-06-03	MDSD / LAS AMERICAS INT'L AP 1006031500/1008301059 AIRCRAFT STAND FROM C-1 TO C-13 LIMITED ACCESS AND EXIT FOR THE FOLLOWING AIRCRAFT TO STAR UP: B-777, B-767, B-757, B-747, B-737, B-707, A-340, A-320, A-319, A-310, A-300, DC-8, DC-10, E-190 AND E-145 DUE TO MEN AND EQUIPMENT WORKING.
A0243-10	10-06-06	MDCY / EL CATEY INT'L AP 1006061530/1007192359 FUEL AVIATION GASOLINE 100/130 NOT AVAILABLE.
A0245-10	10-06-07	MDCY / EL CATEY INT'L AP 1006071945/1008072359 EST DCY DME ON FREQUENCY 115.8 Mhz UNSERVICEABLE DUE TO MAINTENANCE.
A0247-10	10-06-10	MDBH / MARIA MONTEZ INT'L AP 1006101600/1009100000 FIRE AND RESCUE SERVICES DOWNGRADED TO CAT-3.
A0250-10	10-06-13	MDBH / MARIA MONTEZ INT'L AP 1006131200/1009131200 FUEL AVIATION GASOLINE 100 NOT AVAILABLE.
A0251-10	10-06-13	MDBH / MARIA MONTEZ INT'L AP 1006131200/1009131200 FUEL JET A1 NOT AVAILABLE.
A0259-10	10-06-23	MDLR / LA ROMANA INT'L AP 1006232300/1009232200 RUNWAY END IDENTIFIER LIGHT 29 UNSERVICEABLE DUE TO MAINTENANCE.

NR	Date	TEXT
A0260-10	10-06-24	MDCS / SANTO DOMINGO FIR 1006242100/1008242359 TO AVOID UNNECESSARY SEARCH AND RESCUE MISSIONS, AND DUE TO LIMITED COM COVERAGE OF THE PORT AU PRINCE ATC FACILITIES, ALL VISUAL FLIGHT RULES FLYING FROM SANTO DOMINGO FIR INTO PORT AU PRINCE FIR, MUST CANCEL FILED FLIGHT PLAN CROSSING THE BOUNDARY WITH SANTO DOMINGO FLIGHT INFORMATION CENTRE ON FREQUENCY 126.9 SANTO DOMINGO AREA CONTROL CENTRE OR AREA CONTROL FREQUENCY 124.3 OR 127.8 Mhz AND IF NOT POSSIBLE IN ANY OF THE ABOVE FREQUENCIES, CALL BARAHONA TWR ON FREQUENCY 118.5 OR CALL SANTO DOMINGO FLIGHT INFORMATION CENTRE VIA 1809-549-1310 EXT 355.
A0261-10	10-06-25	MDSD / LAS AMERICAS INT'L AP 1006251700/1008251700 TWY E-1 CLOSED FROM APRON TO TWY J DUE TO MEN AND EQUIPMENT WORKING.
A0262-10	10-06-29	MDPC / PUNTA CANA INT'L AP 1006290300/1007021100 JUN 29 AND 30 FROM 0300 TO 1100, JUL 01 AND 02 FROM 0300 TO 1100 MEN AND EQUIPMENT WORKING AT NORTH SIDE RWY 09/27 CAUTION IS ADVISED.
A0268-10	10-06-30	MDPC / PUNTA CANA INT'L AP 1007030330/1007101000 JUL 03 , 05 AND 06 FROM 0330 TO 1000, JUL 07 FROM 0300 TO 1000, JUL 08 FROM 0500 TO 1000, JUL 09 AND 10 FROM 0330 TO 1000 RUNWAY 09/27 CLOSED DUE TO MEN AND EQUIPMENT WORKING.
A0269-10	10-07-01	MDCS / SANTO DOMINGO FIR 1007010000/1007312359 CHECKLIST OF NOTAM SERIE "A" IN FORCE.
<i>This List of Valid NOTAM cancel the last List of Valid NOTAM JUN 2010</i>		