

REPÚBLICA DOMINICANA
INSTITUTO DOMINICANO DE AVIACIÓN CIVIL
GESTION DE INFORMACIÓN AERONÁUTICA (AIM)

Apartado Postal 1180, Tel. 221-7909, Santo Domingo, D.N., AILA, edificio Norge Botello Tel. (809) 274-4322 ext. 2293, 2301 Fax 549-0402

AIM DOMINICAN REPUBLIC
WEB SITE : aip.idac.gov.do
AFTN : MDSYNYX
E-MAIL : ais@idac.gov.do
pub@idac.gov.do



List of valid NOTAM
FEB 2019

THE FOLLOWING NOTAM SERIE "A" STILL IN FORCE AT 1901062359

2017:	0338	0339	NIL							
2018:	0081	0327	0362	NIL						
2019:	0008	0015	0020	0021	0022	0025	0034	0048	0049	NIL

AIS INTEGRATED PACKAGE: LATEST PUBLICATIONS

AIP REGULAR AMDT:	NOV-30-2018	8-18
AIP AIRAC AMDT:	JAN-31-2019	1-19
AIRAC EFFECTIVE DATES:	FEB-28-2019	NIL
CURRENT AIP/ SUP:		2017/2018
GEN:		NIL
ENR:		NIL
AD:		NIL
CURRENT/AIC:		2008/2010/2011/2016/2019
GEN:	JAN-01-2019 FEB-08-2016 JUL-21-2011 AUG-04-2008 NOV-27-2008	No. 01-19 No. 01-16 No. 01-11 No. 02-08 No. 05-08
ENR:	DEC-13-2010 NOV-27-2008 NOV-27-2008	No. 02-10 No. 03-08 No. 04-08
AD:	NOV-27-2008	No. 04-08
Monthly list of valid NOTAM:	FEBRUARY-01-2019	FEB

NR	DATE	TEXT
A0338/17	17-09-28	MDSYNYX / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP 1710120000 / PERM THRESHOLD ELEVATION CHANGED RUNWAY 17 TO 11.99 METRES AND RUNWAY 35 TO 17.69 METRES REFERENCE TO AIP DOMINICAN REPUBLIC, PAGES MDSYNYX AD 2-6 AND 2-15 DATED 12 OCT 17.
A0339/17	17-09-28	MDSYNYX / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP 1710120000 / PERM TOUCHDOWN ZONE ELEVATION CHANGED RUNWAY 17 TO 16.36 METRES AND RUNWAY 35 TO 16.98 METRES REFERENCE TO AIP DOMINICAN REPUBLIC, PAGES MDSYNYX AD 2-6 AND 2-15 DATED 12 OCT 17.

NR	DATE	TEXT
A0081/18	18-04-03	MDCS / SANTO DOMINGO FIR 1804032145 / PERM DAILY SUNRISE / SUNSET PARASAILING ACTIVITY WILL TAKE PLACE IN POLYGON FORMED BY THE JUNCTION THE FOLLOWING COORDINATES: 19°20'14.89"N 069°32'51.39"W 19°20'14.12"N 069°29'27.38"W 19°19'28.16"N 069°29'31.48"W 19°19'37.07"N 069°32'49.74"W LAS TERRENAS BEACH FROM SURFACE TO 300 FEET ABOVE MEAN SEA LEVEL.
A0327/18	18-11-22	MDJB / Dr. JOAQUIN BALAGUER INT'L AP 1811221850 / 1902211900 HGR NDB ON FREQUENCY 300 KHZ UNSERVICEABLE.
A0362/18	18-12-18	MDSI / SAN ISIDRO AIR BASE AP (MIL) 1812191500 / 1903191500 SIS VOR/DME ON FREQUENCY 112.4 MHZ UNSERVICEABLE.
A0008/18	19-01-09	MDCY / EL CATEY INT'L AP 1901091820 / 1902092359 ATIS ON FREQUENCY 132.650 MHZ UNSERVICEABLE DUE TO MAINTENANCE.
A0015/19	19-01-18	MDCS / SANTO DOMINGO FIR 1902280001 / PERM ALL VFR/IFR FLIGHT PLAN AND MOVEMENT MESSAGES RELATING TO TRAFFIC INTO OR VIA THE SANTO DOMINGO FIR, SUBJECT TO RECEIVE AIR TRAFFIC SERVICE, SHALL BE ADDRESSED TO THE UNIQUE ADDRESS MDCSZPZF IN LIEU OF THE PUBLISHED IN AIP, ENR 1.11.
A0020/19	19-01-22	MDST / DEL CIBAO INT'L AP 1901231100 / 1902232000 DAILY 1100 / 2000 MEN AND EQUIPMENT WORKING ON BOTH SIDES RUNWAY 11/29 CAUTION IS ADVISED.
A0021/19	19-01-22	MDPP / PUERTO PLATA INT'L AP 1901231100 / 1902232200 MEN AND EQUIPMENT WORKING ON BOTH SIDES RUNWAY 08/26 CAUTION IS ADVISED.
A0022/19	19-01-23	MDSD / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP 1901231415 / 1904221415 I-CDO INSTRUMENT LANDING SYSTEM GLIDE PATH RUNWAY 17 ON FREQUENCY 329.3 MHZ UNSERVICEABLE DUE TO MAINTENANCE.
A0025/19	19-01-23	MDPP / PUERTO PLATA INT'L AP 1901231828 / 1904221700 PTA VOR ON FREQUENCY 115.1 MHZ UNSERVICEABLE DUE TO MAINTENANCE.
A0034/19	19-01-29	MDSD / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP 1901310000 / 1902142359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 1-19 WITH EFFECTIVE DAY 31 JAN 2019 UPDATE OF THE STANDARD INSTRUMENT DEPARTURE (SID) RNAV RUNWAY 17/35 IN THE JOSE FRANCISCO PEÑA GOMEZ INTERNATIONAL AIRPORT (MDSD).
A0048/19	19-01-31	MDPC / PUNTA CANA INT'L AP 1901311515 / 1902201200 TAXIWAY H CLOSED DUE TO MEN AND EQUIPMENT WORKING.
A0049/18	19-02-01	MDCS / SANTO DOMINGO FIR 1902010048 / 1902282359 EST CHECKLIST OF NOTAM "A" IN FORCE.

This List of Valid NOTAM cancel the last List of Valid NOTAM JAN 2019