

REPÚBLICA DOMINICANA
INSTITUTO DOMINICANO DE AVIACIÓN CIVIL
GESTION DE INFORMACIÓN AERONÁUTICA (AIM)

Apartado Postal 1180, Tel. 221-7909, Santo Domingo, D.N., AILA, edificio Norge Botello Tel. (809) 274-4322 ext. 2293, 2301 Fax 549-0402

AIM DOMINICAN REPUBLIC
WEB SITE : aip.idac.gov.do
AFTN : MDSYNYX
E-MAIL : ais@idac.gov.do
pub@idac.gov.do



List of valid NOTAM
NOV 2018

THE FOLLOWING NOTAM SERIE "A" STILL IN FORCE AT 1811022359

2017:	0338	0339	NIL											
2018:	0081	0231	0262	0272	0275	0276	0277	0280	0282	0287	0288	0295	0296	NIL

AIS INTEGRATED PACKAGE: LATEST PUBLICATIONS

AIP REGULAR AMDT:	NOV-30-2012 MAY-30-2018	7-12 NIL
AIP AIRAC AMDT:	SEP-13-2018	4-18
AIRAC EFFECTIVE DATES:	NOV-08-2018 DEC-06-2018	NIL NIL
CURRENT AIP/ SUP:		2017/2018
GEN:		NIL
ENR:		NIL
AD:		NIL
CURRENT/AIC:		2008/2010/2011/2016/2018
GEN:	JAN-01-2018 FEB-08-2016 JUL-21-2011 AUG-04-2008 NOV-27-2008	No. 01-18 No. 01-16 No. 01-11 No. 02-08 No. 05-08
ENR:	DEC-13-2010 NOV-27-2008 NOV-27-2008	No. 02-10 No. 03-08 No. 04-08
AD:	NOV-27-2008	No. 04-08
Monthly list of valid NOTAM:	NOVEMBER-01-2018	NOV

NR	DATE	TEXT
A0338/17	17-09-28	MDSD / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP 1710120000 / PERM THRESHOLD ELEVATION CHANGED RUNWAY 17 TO 11.99 METRES AND RUNWAY 35 TO 17.69 METRES REFERENCE TO AIP DOMINICAN REPUBLIC, PAGES MDSD AD 2-6 AND 2-15 DATED 12 OCT 17.
A0339/17	17-09-28	MDSD / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP 1710120000 / PERM TOUCHDOWN ZONE ELEVATION CHANGED RUNWAY 17 TO 16.36 METRES AND RUNWAY 35 TO 16.98 METRES REFERENCE TO AIP DOMINICAN REPUBLIC, PAGES MDSD AD 2-6 AND 2-15 DATED 12 OCT 17.

NR	DATE	TEXT
A0081/18	18-04-03	MDCS / SANTO DOMINGO FIR 1804032145 / PERM DAILY SUNRISE / SUNSET PARASAILING ACTIVITY WILL TAKE PLACE IN POLYGON FORMED BY THE JUNCTION THE FOLLOWING COORDINATES: 19°20'14.89"N 069°32'51.39"W 19°20'14.12"N 069°29'27.38"W 19°19'28.16"N 069°29'31.48"W 19°19'37.07"N 069°32'49.74"W LAS TERRENAS BEACH FROM SURFACE TO 300 FEET ABOVE MEAN SEA LEVEL.
A0231/18	18-08-23	MDCY / EL CATEY INT'L AP 1808231600 / 1811232359 PAPI LIGHT RUNWAY 25 UNSERVICEABLE DUE TO MAINTENANCE.
A0262/18	18-09-19	MDSI / SAN ISIDRO AIR BASE AP (MIL) 1809191300 / 1812191400 SIS VOR/DME ON FREQUENCY 112.4 MHZ UNSERVICEABLE.
A0272/18	18-10-04	MDPC / PUNTA CANA INT'L AP 1810041800 / 1811301600 MEN AND EQUIPMENT WORKING ON TAXIWAY A AND TAXIWAY H, CAUTION IS ADVISED.
A0275/18	18-10-09	MDPP / PUERTO PLATA INT'L AP 1810101000 / 1811102300 DAILY 1000/2300 MEN AND EQUIPMENT WORKING ON RUNWAY 08/26, CAUTION IS ADVISED.
A0276/18	18-10-10	MDLR / CASA DE CAMPO INT'L AP 1810101940 / PERM THE STRENGTH OF THE RUNWAY 11/29 CHANGED TO PAVEMENT CLASSIFICATION NUMBER 86/R/B/W/T.
A0277/18	18-10-11	MDPC / PUNTA CANA INT'L AP 1810111700 / 1811302100 RUNWAY 09/27 CLOSED DUE TO MEN AND EQUIPMENT WORKING.
A0280/18	18-10-14	MDPP / PUERTO PLATA INT'L AP 1810141355 / 1901111355 PTA VOR ON FREQUENCY 115.1 MHZ UNSERVICEABLE DUE TO MAINTENANCE.
A0282/18	18-10-16	MDPC / PUNTA CANA INT'L AP 1810161400 / 1811152100 TAXIWAY G AND H CLOSED DUE TO MEN AND EQUIPMENT WORKING.
A0287/18	18-10-22	MDJB / Dr. JOAQUIN BALAGUER INT'L AP 1810221445 / 1811221925 HGR NDB ON FREQUENCY 300 KHZ UNSERVICEABLE.
A0288/18	18-10-22	MDSB / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP 1810221501 / 1901221501 I-CDO INSTRUMENT LANDING SYSTEM GLIDE PATH RUNWAY 17 ON FREQUENCY 329.3 MHZ UNSERVICEABLE DUE TO MAINTENANCE.
A0295/18	18-10-31	MDSB / JOSÉ FRANCISCO PEÑA GÓMEZ INT'L AP 1810312100 / 1811302100 AIRCRAFT STAND A-3 CLOSED DUE TO MEN EQUIPMENT WORKING.
A0296/18	18-11-01	MDCS / SANTO DOMINGO FIR 1811010010 / 1811302359 EST CHECKLIST OF NOTAM "A" IN FORCE.
<i>This List of Valid NOTAM cancel the last List of Valid NOTAM OCT 2018</i>		